

PSX™60 Adhesive Kit

Epoxy siloxane electrically conductive adhesive for bonding fiberglass pipe and fittings



OIL & GAS



CHEMICAL & INDUSTRIAL



MARINE



OFFSHORE



FUEL HANDLING



MINING

Description

The PSX 60 epoxy adhesive kit contains an adhesive resin, hardener, mixing spatula, and assembly instructions. The adhesive resin (Part A) is a black paste with sand filler and conductive fibers. The adhesive hardener (Part B) is a grayish-white paste. The mixed adhesive color is black. PSX 60 is a two-part epoxy siloxane adhesive formulated for permanently bonding Quick-Lock™ or taper-taper joints on fiberglass-reinforced pipe and fittings. PSX 60 can be used to connect most epoxy and phenolic piping systems.

Instructions

Prior to handling, read all Toxicity, Precaution and First Aid information below. Before mixing the adhesive, ensure that the bonding surfaces are correctly prepared and are clean and dry. Open the resin and hardener containers. Using the mixing spatula, scrape all of the hardener into the resin container. Mix the resin and the hardener with the spatula for at least 60 seconds. Scrape the sides, bottom and lid of the resin container occasionally to get all of the hardener into the mix. Never attempt to split a kit or heat the hardener. The resin and the hardener have been packaged at the correct ratio for optimum adhesive performance.

Apply a uniform coat of the mixed adhesive to both bonding surfaces and draw the parts firmly together. Detailed joint assembly instructions may be found in Quick-Lock Installation Instructions, and Bell x Spigot Installation Instructions.

Pot Life and Cure Time

For installations with service temperatures below 180°F (82°C) and pressures below 150 psi (1.03 MPa), PSX 60 bonds can be put into service with ambient temperature cures as indicated in the table. However, it is highly recommended that an external heat source be used to force cure the adhesive. The adhesive and bonding surfaces should be warmed to 70°F (21°C) prior to mixing and applying the adhesive. Adhesive may be force cured using an NOV Fiber Glass Systems approved heating blanket. The table also indicates the pot life (working time) of the adhesive at various temperatures. The pot life is the time from the initial mixing of the resin and hardener until the adhesive in the container begins to thicken and is no longer usable.

For systems with anticipated service temperatures above 180°F (82°C) or operating pressures over 150 psi (1.03 MPa), or when installing any system at ambient temperatures below 40°F (5°C), the adhesive joint must be cured with an external heat source. A heat cure using an NOV Fiber Glass Systems approved electric heating blanket is recommended. The heat cure may be applied at any time after the bond is made and before the line is tested or put into service. The heat may be applied immediately after making the bond while the adhesive is still liquid or after it has gelled to a solid.

Minimum cure times of 30 minutes for 1 through 6 inch pipe and 45 minutes for 8 through 16 inch lines are recommended. Even after the adhesive has solidified at ambient temperatures, heat curing will enhance the chemical cross-linking of the adhesive, increasing the strength, temperature resistance and corrosion resistance of the adhesive. When used in fire protection service all joints must be force-cured with an external heat source regardless of ambient temperature.

Ambient Temperature		Adhesive Pot Life	Minimum Joint Cure Time	Minimum Time to Move
°F	°C	minutes	hours	hours
40	5	70	12	11
60	16	40	7	6
70	21	30	5	4
80	27	20	4	3
100	38	8	3	2

First Aid

In case of contact

Eyes: Immediately flush eyes with plenty of water for at least 15 minutes. Call a physician.

Skin: Wash skin with soap and water.

Clothing: Remove contaminated clothing and wash before reuse.

Inhalation: Remove to fresh air. Give oxygen or artificial respiration if necessary.

Ingestion: If catalyst is swallowed and person is conscious, give plenty of water or milk to drink. Do not induce vomiting. Call a physician. If resin is swallowed, give 100 grams (about 1/4 lb) activated charcoal slurry in water.

Do not induce vomiting. Call a physician.

Call Chem Tel for chemical emergencies, spills:

Hotline/SDS Fax Access: 800-255-3924

Internationally: +01-813-248-0585

PSX60 adhesive kits are available in 3 fluid oz. and 6 fluid oz. sizes. The values in this table are based on the quantity of adhesive required by an experienced crew working at a temperature of 80°F (27°C).

Adhesive Kit per Quick-Lock Joint

Adhesive Kit Size	3 oz								6 oz			
	Nominal Pipe Size (in/mm)	1 / 25	1½ / 40	2 / 50	3 / 80	4 / 100	5 / 125	6 / 150	8 / 200	10 / 250	12 / 300	14 / 350
Number of Kits	½	½	¼	⅓	½	½	1	1	1	1½	1½	2

Adhesive Kit per Taper/Taper Joint

Adhesive Kit Size	Nominal Pipe Size		BS2410	BS2412	BS2414 BS3000* BS3200*	BS2416* RTHP16* GTHP16*	BS2420 RTHP20* GTHP20* BS3300*	BS2425 RTHP25* GTHP25*	BS2432 RTHP32* GTHP32*	BS2440 RTHP40* GTHP40*	BS2450	Marine Taper 2000M/7000M
	in	mm										
3 oz	2	50	⅓	⅓	⅓	⅓	⅓	⅓	⅓	⅓	⅓	-
	3	80	⅓	⅓	⅓	⅓	⅓	½	½	½	1	-
	4	100	½	½	½	½	½	½	½	1	1	-
	6	150	½	½	½	½	1	1	1	2	2	-
	8	200	1	1	1	1	1	2	2	2	2	1
6 oz	10	250	½	1	1	1	1	1	1	2	2	1
	12	300	1	1	1	1	1	2	2	2	3	1
	14	350	1	1	2	2	2	2	2	3	3	2
	16	400	1	1	2	2	2	2	2	3	4	2
	18	450	2	2	2	2	2	2	3	4	5	3
	20	500	2	2	2	3	3	3	4	5	6	3
	24	600	2	3	3	3	3	4	5	7	-	4
	28	700	3	3	4	4	5	6	-	-	-	5
	30	750	3	4	5	5	6	7	-	-	-	5
	32	800	3	4	4	6	6	8	-	-	-	6
	36	900	4	6	6	7	7	-	-	-	-	6
	40	1000	5	7	7	7	-	-	-	-	-	7
	42	1050	-	-	-	8	-	-	-	-	-	-

BS=Bondstrand™; RTHP=Red Thread™ HP; GTHP=Green Thread™ HP
 *Not all sizes available

Storage

Do not store kits in areas above 100°F (38°C) or below 32°F (0°C), or in the direct sunlight in warm weather. In cold weather warm the resin to at least 70°F (21°C) but not above 100°F (38°C) to permit good mixing and easier application. Do not use adhesive past its expiration date.

Toxicity and Precautions

Hardener: The hardener is irritating to skin, eyes and respiratory tract. It is toxic orally and may cause sensitization. Avoid contact with eyes, skin or clothing. Avoid breathing vapors. Wear rubber gloves, protective apron and NIOSH approved respirator. Wash thoroughly after handling.

Resin: The resin may be mildly irritating to skin, eyes and respiratory tract. Avoid contact with eyes, skin or clothing. Avoid breathing vapors. Wear rubber gloves and eye protection. Wash thoroughly after handling.

National Oilwell Varco has produced this brochure for general information only, and it is not intended for design purposes. Although every effort has been made to maintain the accuracy and reliability of its contents, National Oilwell Varco in no way assumes responsibility for liability for any loss, damage or injury resulting from the use of information and data herein nor is any warranty expressed or implied. Always cross-reference the bulletin date with the most current version listed at the web site noted in this literature.

Fiber Glass Systems

17115 San Pedro Avenue, Ste 200
 San Antonio, Texas 78232 USA
 Phone: 210 477 7500
 Fax: 210 477 7560

© 2017 National Oilwell Varco All Rights Reserved
 ADH4720ENG June 2017